




7529.0010

Onderdelen informatie
Erzatzteil information
Spare part information
Information de pièces







POS:	Art.No.:	Omschrijving:	Aantal:
1		pressing plate	2
2	9288.0030	vacuum lid	1
3	9288.0050	square handle	1
4		seal ring for square handle	2
5		gasket of mounted plate	1
6		mounted plate for heat-sealing foam	1
7	9288.0200	heat seal gasket	1
8	9288.0210	outlet valve	1
9	9288.0220	400Z pump	1
10		Connector nut	1
11	9288.0150	connector for pump suction	1
12	9288.0190	four-way connector	1
13	9288.0170	Tee connector	1

POS:	Art.No.:	Omschrijving:	Aantal:
14	9288.0230	Alien Tee	1
15	9288.0180	inlet valve	1
16	9288.0150	0626L magnetic valve	1
17		cord holder	1
18		Insulating spacer for motor	1
19	9288.0020	motor PCB	1
20		rubber pad	4
21		insulating spacer for switch power Board	1
22	9288.0010	Power Board	1
23	9288.0240	extraction joint of vacuum chamber	1
24		seal ring of suction connector	1
25	9288.0240	connector for inlet hole	1
26		Vacuum chamber	1

POS:	Art.No.:	Omschrijving:	Aantal:
27		Clamp	1
28		clamp fixing cover	4
29	9288.0060	seal bar (assembly)	1
30	9288.0130	Tee connector	1
31		M14 nuts	2
32	9288.0140	up-down piston (assembly)	2
33		rear cover board	1
34		damping gasket of machine body	9
35	9288.0120	mounted plate for control panel	1
36	9288.0120	control board	1
37	9288.0110	Pressure gauge	1
38	9288.0120	membrane switch	1
39		Main body	1

POS:	Art.No.:	Omschrijving:	Aantal:
40		jr-101 power socket	1
41		power cord	1
42	9288.0250	rubber foot	4
43		Base plate	1
44		fixing panel	1
45	9288.0100	Micro Switch assembly	1
46	9288.0040	sealing ring	1
47	9288.0070	left swivel arm assembly	1
48		M10 nuts	4
49	9288.0080	right swivel arm assembly	1